Model:	Platina Integrated
Version:	V1.49
Issue date:	10th Dec 2026
Type:	Public

New Features

No new features are listed for this release.

Fixed:

Reduced the upper limit for noise-floor detection to accommodate the GD305 MCU.
Fixed an out-of-bounds issue in CEC reception.

Additional information

Firmware update instructions.
1. Turn off the power supply to the device (rear panel mains switch)
2. Prepare a FAT32-formatted USB drive. Create a folder named 'PINT' on the drive and place the update file 'PINT.bin' inside that folder.
3. Insert the USB drive to the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold front panel standby button.
5. Keep holding the front-panel standby button while switching on the device using the rear-panel mains switch.
6. Release the standby button and the display will show 'upgrade processing'.
7. Allow the device to apply the software update. This may take a few seconds.
8. When update is complete, the device is ready to use.

All rights reserved ©IAG Group Ltd.
IAG reserves the right to alter the design and specifications without any notice.
Quad is a member of the International Audio Group. www.quad-hifi.co.uk

Change history

V1.48
1. Fixed a failure to read VU data after calibration.

V1.46
1. Added ARC Auto Switch function

V1.45
1. Fixed Volume-setting bug occurring when AV direct mode is enabled.

V1.44
1. Add AV direct option to AUX2
2. Remove Power On Limit = Off option

V1.43
1. Fixed Upsampling setting bug

V1.42
1. Improved HDMI ARC performance

V1.41
1. First Release

All rights reserved ©IAG Group Ltd.
IAG reserves the right to alter the design and specifications without any notice.
Quad is a member of the International Audio Group. www.quad-hifi.co.uk